

	A	B	C	D	E	F	G	H	I	J	K	L
1	PART NUMBER	DESCRIPTION	1990new	bravekozak	daledwilson	iriegnome	sketchman	PRICE	TOTAL	EXT	Comments	
2	<a href="#">KKY0146090</a>	BOOT - H/K - SHUMA						\$1.30	0	\$0.00	Shifter bottom boot	
3	<a href="#">MD002500H0</a>	BRKT-F.BUMP.,LH		1				\$10.29	1	\$10.29	Left Bumper Cover Me	
4	<a href="#">MD002500G0</a>	BRKT-F.BUMP.,RH		1				\$8.00	1	\$8.00	Right Bumper Cover M	
5	<a href="#">KKY0146041</a>	BUSH - Hyundai/Kia - PRIDE						\$1.43		\$0.00	Gear Shifter Stabilize	
6	<a href="#">KK16651586</a>	CAP		1				\$1.43	1	\$1.43	HI Stop Lamp Cap	
7	<a href="#">KK1706937304</a>	CAP-ARM REST		2				\$0.14	2	\$0.28		
8	<a href="#">KK1706937330</a>	CAP-ARM REST		2				\$0.14	2	\$0.28		
9	<a href="#">MB09367366A</a>	CAP-SEALING		2				\$0.48	2	\$0.96	WS Wiper shaft Rubb	
10	<a href="#">MD00167366</a>	CAP-SEALING					2	\$0.71	2	\$1.42	WS Wiper shaft Rubb	
11	<a href="#">OK2A115355A</a>	CAP-SUB TANK		3				\$2.43	3	\$7.29	WS Washer tank lid	
12	<a href="#">MDA0167483</a>	CAP-TANK		1				\$3.67	1	\$3.67	Radiator Reservoir Lid	
13	<a href="#">KKY0158605</a>	CHANNEL-GLASS RUN,RH						\$10.29		\$0.00	Right Door Glass Cha	
14	<a href="#">KKY0159605</a>	CHANNEL-GLASS RUN,RH						\$10.29		\$0.00	Left Door Glass Chan	
15	<a href="#">KK1365572009</a>	CLOCK BEZEL						\$4.33	0	\$0.00		
16	<a href="#">MB30115172B</a>	COVER-THERMOSTAT		1				\$8.76	1	\$8.76	Thermostat Housing	
17	<a href="#">MB00176641</a>	COVER-WIPER ARM		1				\$0.71	1	\$0.71	WS Wiper Arm Plastic	
18	<a href="#">KK1501851X</a>	H.G.U SUB ASSY		1				\$8.76	1	\$8.76	Temperature Sensor	
19	<a href="#">KK15056693A</a>	HOLDER-BONNET STAY					2	\$0.67	2	\$1.34		
20	<a href="#">KKY0115261</a>	HOSE - BYPASS						\$0.71		\$0.00	Water Bypass Hose (M	
21	<a href="#">KK15009010</a>	KEY SET					1	\$70.71	1	\$70.71	Key Set (More that on	
22	<a href="#">KKY015831604</a>	KNOB-INNER LOCK		2				\$1.43	2	\$2.86		
23	<a href="#">KKY0167360</a>	LINK ASSY-WIPER,FR					1	\$25.43	1	\$25.43	WS Wiper Linkage - F	
24	<a href="#">KKY0156620B</a>	LOCK ASSY-BONNET					1	\$11.43	1	\$11.43	Rear Hatch Standard	
25	<a href="#">KKY0167510</a>	NOZZLE-WASHER		1				\$2.38	1	\$2.38	WS Washer nozzle	
26	<a href="#">KKY0176605A</a>	NUT					2	\$0.95	2	\$1.90	Avella Rear Wiper mo	
27	<a href="#">K999400801B</a>	NUT-FLANGE H/K TERRACAN					2	\$0.48	2	\$0.96	Holds WS Wiper on	
28	<a href="#">K9954103801</a>	O-RING, DISTRIBUTOR		10				\$0.48	10	\$4.80	Distributor O-Ring	
29	<a href="#">KKY0176604</a>	OUTER-BUSH					2	\$1.90	2	\$3.80	WS Wiper Bushing Fr	
30	<a href="#">MH00143443</a>	PACKING H/K CREDOS		2				\$0.71	2	\$1.42	Manual Trans (Brake /	
31	<a href="#">MDA0141711</a>	PAD-ACCELERATOR PEDAL - H/K - RIO					2	\$0.71	2	\$1.42	Accelerator pedal (Fit	
32	<a href="#">MB09243028</a>	PAD-PEDAL - H/K - AVELLA					4	\$1.43	4	\$5.72	Brake and clutch peda	
33	<a href="#">KKY0155210B00</a>	PANEL ASSY-CTR			1	1		\$15.71	2	\$31.42	Radio/Htr/AC Bezel	
34	<a href="#">KKY0146047</a>	PIPE-D H/K CREDOS		4				\$0.71	4	\$2.84	Sleeve inside shifter s	
35	<a href="#">KK12B69391B04</a>	REST-ARM, LH						\$17.14	0	\$0.00	LH Power Window Arr	
36	<a href="#">KK12B69371B04</a>	REST-ARM, RH		1				\$16.00	1	\$16.00	RH Power Window Ar	

	A	B	C	D	E	F	G	H	I	J	K	L
37	<a href="#">KKY0246081</a>	SEAL BALL						\$1.43	0	\$0.00		
38	<a href="#">MD06133699</a>	SLEEVE- BOLT,SUB		2				\$0.71	2	\$1.42		
39	<a href="#">MB09233698</a>	SLEEVE-BOLT H/K AVELLA		2				\$0.71	2	\$1.42		
40	<a href="#">KK135500A500</a>	STRIPE-F.BUMPER	1					\$2.90	1	\$2.90	Front Bumper Stripe K	
41	<a href="#">KK12B6637004</a>	SW ASSY-P/WINDOW PASS						\$14.86	0	\$0.00	Power Window Switch	
42	<a href="#">KK12B6635004</a>	SWITCH ASSY-P/WDO MAIN						\$22.86	0	\$0.00	Power Window Switch	
43	<a href="#">KK19166120D</a>	SWITCH-ASSY-MULTIFUNCITON					1	\$73.07	1	\$73.07	Combo switch with int	
44	<a href="#">KKY016824189</a>	TRIM-C.PILLAR,LH		1				\$7.01	1	\$7.01		
45	<a href="#">KKY016822189</a>	TRIM-C.PILLAR,RH		1				\$7.01	1	\$7.01		
46	<a href="#">KKY026842104</a>	VESSEL-IN,.LOCK						\$0.48	0	\$0.00	Door Lock Pull Surrou	
47	<a href="#">KKY0156750</a>	WTHSTP.-SHROUD SEAL	1					\$7.81	1	\$7.81	Rubber strip under fro	
48	<a href="#">MD00172761F</a>	WTHSTP-QTR,RH		1				\$15.62	1	\$15.62	Right Rear Glass Win	
49												
50										\$352.54		
51			\$10.71	\$113.21	\$15.71	\$15.71	\$197.20	\$352.54				

	M	N	O
1			
2			
3	Metal Bumper Brace		
4	Metal Bumper Brace		
5	r Bushing		
6			
7			
8			
9	er Cap		
10	er Cap		
11			
12			
13	hnel Rubber		
14	hnel Rubber		
15			
16			
17	Cover		
18			
19			
20	near Thermostat Housing)		
21	e - be sure its correct)		
22			
23	ront		
24	lock assy		
25			
26	for nut		
27			
28			
29	one		
30	Clutch Pedals)		
31	Festiva?)		
32	l - manual		
33			
34	tabilizer bushing KKY01460441		
35	n Rest for LHD cars		
36	m Rest for LHD cars		

	M	N	O
37			
38			
39			
40	it		
41	(PASS R)		
42	(Main L&R)		
43	ermittent		
44			
45			
46	nd (last one were olive drab color		
47	ht of hood		
48	low Seal		
49			
50			
51			